CITY OF COLUMBUS COLUMBUS DIVISION OF FIRE

Fire Prevention Bureau 3639 Parsons Avenue Columbus, Ohio 43207 614-645-7641, Ext. 75607 614-645-6637 Fax



REQUIREMENTS TO PASS TYPE B HOME INSPECTION

- 1. A 1A-10BC **ABC** fire extinguisher must be in the kitchen area. A person must be able to access the fire extinguisher without passing the stove when entering the kitchen. The fire extinguisher should be visible from anywhere in the kitchen.
- 2. Smoke detectors must be present on each level in the structure.

They should be mounted on the ceilings at least 4 inches away from any wall.

If they must be mounted on a wall they should be between 4 to 12 inches away from the ceiling.

If a detector is mounted on a peaked or sloped ceiling it shall be at least 4 inches from the peak but not more than 3 feet away.

The smoke detector in the basement should be on the ceiling as close as possible to the basement stairs.

Smoke detectors should not be mounted in a corner, but should be out in the open to avoid dead air space.

The first floor smoke detector should <u>not</u> be mounted in the kitchen. <u>It should be just outside the entrance to the kitchen.</u>

The second floor smoke detector should be in the hallway between the bedrooms.

- 3. Nothing should be stored within 3 feet of the furnace or hot water tank.
- 4. An evacuation plan must be posted on each level of the home with a diagram of each floor in the structure showing the escape routes to the exits. It should include the address of a neighboring home on the same side of the street, in front of which would be the safe meeting place. Foster homes are also required to post a Fire Drill Schedule.
- 5. Anyone providing care for children ages 6 and under must cover <u>all</u> unused electrical outlets (including surge protectors) with plastic covers
- 6. Remove all poisons and corrosives from lower cabinets and under sinks or secure them with child proof locks.
- 7. All structures should be ready for immediate occupancy and should include furniture.
- 8. All pets must be secured before fire inspectors will enter the premises.